

```
#define FOSC      (4000000L)
#define SCI_EIGHT  (0)
#define SCI_NINE   (1)

unsigned char    sci_Init(unsigned long int, unsigned char);

//void          sci_PutByte(unsigned char);
void            putch(unsigned char);

//unsigned char sci_GetByte(void);
unsigned char    getch(void);

void            sci_PutNinth(unsigned char);
unsigned char    sci_GetNinth(void);
unsigned char    sci_GetFERR(void);
unsigned char    sci_CheckOERR(void);
```